

- when it has to be **right**

Leica Geosystems Release Notes

Product Leica RTC360 and RTC360 LT

Date 10th September 2024

From TLS Hardware Product Management

Leica RTC360 3D Laser Scanner - Firmware v6.05



Leica Geosystems AG Heinrich-Wild-Strasse CH-9435 Heerbrugg Schweiz www.leica-geosystems.com These Release Notes contain important information about the new Leica RTC360 firmware v6.05.

The new firmware can be obtained from your local Leica Geosystems Selling Unit or can be downloaded from the myWorld Customer Portal: <u>myworld-</u> <u>portal.leica-geosystems.com</u>

myWorld

WHAT'S NEW

This is an engineering release to fix the following issues from firmware v6.04.

1. Production improvements and background bug fixes

This firmware supports some internal production improvements and contains background bug fixes not visible to the user.

FIRMWARE INSTALLATION

- The new firmware v6.05 can be installed on any Leica RTC360 or RTC360 LT laser scanner, independent of any previous firmware version.
- Compatibility with Leica Cyclone and Cyclone REGISTER 360 PLUS
 - Cyclone REGISTER 360 PLUS v2023.0.0 or higher is required to support the Data Security workflow
 - Cyclone v2023.0.0 or higher is compatible with firmware v6.05 but does not support the Data Security workflow
- Compatibility with Leica Cyclone FIELD 360
 - It is always recommended to only use the latest version of Cyclone FIELD 360 (currently version 5.1.0)